


CONDITIONS DE COUPE - CONTOURNAGE



$$n [\text{tr/min}] = \frac{V_c [\text{m/min}] \times 1000}{\pi \times D_1 [\text{mm}]}$$


$$V_f [\text{mm/min}] = n [\text{tr/min}] \times f_z [\text{mm}] \times Z$$

Avance par dent $f_z [\text{mm}]$

Matières à usiner		CARBURE		C-TOP		ap [mm]	ae [mm]	Avance par dent $f_z [\text{mm}]$					
		Vc [m/min]	Vc [m/min]	Vc [m/min]	Vc [m/min]			Ø D ₁ 0.10 - 0.40	Ø D ₁ 0.40 - 1.00	Ø D ₁ 1.00 - 1.50	Ø D ₁ 1.50 - 3.00	Ø D ₁ 3.00 - 6.00	Ø D ₁ 6.00 - 12.00
P	Acier non allié / faiblement allié	< 600 N/mm ²		100 200		<1.5 x ØD ₁	<0.40 x ØD ₁	0.0013 - 0.0075	0.005 - 0.019	0.010 - 0.028	0.014 - 0.053	0.026 - 0.105	0.049 - 0.195
P	Acier non allié / faiblement allié	600 - 1500 N/mm ²		80 170		<1.5 x ØD ₁	<0.30 x ØD ₁	0.0011 - 0.0056	0.004 - 0.017	0.009 - 0.025	0.012 - 0.046	0.023 - 0.092	0.043 - 0.172
P	Acier de décolletage au plomb			120 200		<1.5 x ØD ₁	<0.40 x ØD ₁	0.0015 - 0.0075	0.006 - 0.023	0.012 - 0.034	0.017 - 0.063	0.032 - 0.126	0.059 - 0.234
P	Acier fortement allié	700 - 1500 N/mm ²		70 100		<1.5 x ØD ₁	<0.30 x ØD ₁	0.0010 - 0.0070	0.004 - 0.015	0.008 - 0.023	0.011 - 0.042	0.021 - 0.084	0.039 - 0.156
M	Acier inoxydable	400 - 700 N/mm ²		80 110		<1.5 x ØD ₁	<0.30 x ØD ₁	0.0010 - 0.0060	0.004 - 0.015	0.008 - 0.023	0.011 - 0.042	0.021 - 0.084	0.039 - 0.156
M	Acier inox. DUPLEX, acier austénitique inox. sans nickel > 800 N/mm ²			50 80		<1.5 x ØD ₁	<0.30 x ØD ₁	0.0008 - 0.0045	0.003 - 0.011	0.006 - 0.017	0.008 - 0.032	0.016 - 0.063	0.029 - 0.117
K	Fonte grise / Fonte à graphite sphéroïdal perlite	< 250 HB	120 150	160 200		<1.5 x ØD ₁	<0.40 x ØD ₁	0.0015 - 0.0075	0.006 - 0.023	0.012 - 0.034	0.017 - 0.063	0.032 - 0.16	0.059 - 0.234
K	Fonte alliée / Fonte à graphite sphéroïdal perlite	> 250 HB	100 130	130 170		<1.5 x ØD ₁	<0.30 x ØD ₁	0.0011 - 0.0056	0.004 - 0.017	0.009 - 0.025	0.012 - 0.046	0.023 - 0.092	0.043 - 0.172
K	Fonte à graphite sphéroïdal ferritique / Fonte malléable		80 110	110 150		<1.5 x ØD ₁	<0.30 x ØD ₁	0.0011 - 0.0056	0.004 - 0.017	0.009 - 0.025	0.012 - 0.046	0.023 - 0.092	0.043 - 0.172
S	Super alliages / Acier inox. réfractaire	Inconel Nimonic Hastelloy	20 45	30 60		<1.5 x ØD ₁	<0.15 x ØD ₁	0.0005 - 0.0030	0.002 - 0.008	0.004 - 0.011	0.006 - 0.021	0.011 - 0.042	0.020 - 0.078
S	Titane, alliage de titane		45 75	50 80		<1.5 x ØD ₁	<0.30 x ØD ₁	0.0013 - 0.0075	0.005 - 0.019	0.010 - 0.028	0.014 - 0.053	0.026 - 0.105	0.049 - 0.195
N	Alliage de cuivre / bonne usinabilité (laiton - bronze)		90 130	120 200		<1.5 x ØD ₁	<0.40 x ØD ₁	0.0020 - 0.0120	0.008 - 0.030	0.016 - 0.045	0.023 - 0.084	0.042 - 0.168	0.078 - 0.312
N	Alliage de cuivre / usinabilité difficile / Bronze à l'aluminium (Ampco)	(CuAlFe)	70 120	80 140		<1.5 x ØD ₁	<0.40 x ØD ₁	0.0013 - 0.0075	0.005 - 0.019	0.010 - 0.028	0.014 - 0.053	0.026 - 0.105	0.049 - 0.195
N	Or, argent		140 190	150 200		<1.5 x ØD ₁	<0.40 x ØD ₁	0.0013 - 0.0075	0.005 - 0.019	0.010 - 0.028	0.014 - 0.053	0.026 - 0.105	0.049 - 0.195

 $D_1 \leq 0.1 \text{ mm} \Rightarrow (ap \& ae) -95 \%$ $D_1 \leq 0.2 \text{ mm} \Rightarrow (ap \& ae) -85 \%$ $D_1 \leq 0.3 \text{ mm} \Rightarrow (ap \& ae) -70 \%$ $D_1 \leq 0.4 \text{ mm} \Rightarrow (ap \& ae) -50 \%$ $D_1 \leq 0.5 \text{ mm} \Rightarrow (ap \& ae) -25 \%$

CONDITIONS DE COUPE - RAINURAGE



$$n [\text{tr/min}] = \frac{V_c [\text{m/min}] \times 1000}{\pi \times D_1 [\text{mm}]}$$


$$V_f [\text{mm/min}] = n [\text{tr/min}] \times f_z [\text{mm}] \times Z$$

Avance par dent $f_z [\text{mm}]$

Matières à usiner		CARBURE		C-TOP		ap [mm]	ae [mm]	Avance par dent $f_z [\text{mm}]$					
		Vc [m/min]	Vc [m/min]					Ø D ₁ 0.10 - 0.40	Ø D ₁ 0.40 - 1.00	Ø D ₁ 1.00 - 1.50	Ø D ₁ 1.50 - 3.00	Ø D ₁ 3.00 - 6.00	Ø D ₁ 6.00 - 12.00
P	Acier non allié / faiblement allié	< 600 N/mm ²		75 150		<1.5 x ØD ₁	<1 x ØD ₁	0.0006 - 0.0038	0.0025 - 0.009	0.005 - 0.014	0.007 - 0.026	0.013 - 0.053	0.013 - 0.088
P	Acier non allié / faiblement allié	600 - 1500 N/mm ²		60 130		<1.2 x ØD ₁	<1 x ØD ₁	0.0006 - 0.0028	0.0022 - 0.008	0.004 - 0.012	0.006 - 0.023	0.012 - 0.046	0.011 - 0.077
P	Acier de décolletage au plomb			90 150		<1.5 x ØD ₁	<1 x ØD ₁	0.0008 - 0.0038	0.0030 - 0.011	0.006 - 0.017	0.008 - 0.032	0.016 - 0.063	0.015 - 0.105
P	Acier fortement allié	700 - 1500 N/mm ²		50 75		<1 x ØD ₁	<1 x ØD ₁	0.0005 - 0.0035	0.0020 - 0.008	0.004 - 0.011	0.006 - 0.021	0.011 - 0.042	0.010 - 0.070
M	Acier inoxydable	400 - 700 N/mm ²		60 80		<1 x ØD ₁	<1 x ØD ₁	0.0005 - 0.0030	0.0020 - 0.008	0.004 - 0.011	0.006 - 0.021	0.011 - 0.042	0.010 - 0.070
M	Acier inox. DUPLEX, acier austénitique inox. sans nickel > 800 N/mm ²			40 60		<0.8 x ØD ₁	<1 x ØD ₁	0.0004 - 0.0023	0.0015 - 0.006	0.003 - 0.008	0.004 - 0.016	0.008 - 0.032	0.008 - 0.053
K	Fonte grise / Fonte à graphite sphéroïdal perlite	< 250 HB	90 160	120 200		<1.5 x ØD ₁	<1 x ØD ₁	0.0008 - 0.0038	0.0030 - 0.011	0.006 - 0.017	0.008 - 0.032	0.016 - 0.063	0.015 - 0.105
K	Fonte alliée / Fonte à graphite sphéroïdal perlite	> 250 HB	75 100	90 130		<1 x ØD ₁	<1 x ØD ₁	0.0006 - 0.0028	0.0022 - 0.008	0.004 - 0.012	0.006 - 0.023	0.012 - 0.046	0.011 - 0.077
K	Fonte à graphite sphéroïdal ferritique / Fonte malléable		60 80	80 110		<1 x ØD ₁	<1 x ØD ₁	0.0006 - 0.0028	0.0022 - 0.008	0.004 - 0.012	0.006 - 0.023	0.012 - 0.046	0.011 - 0.077
S	Super alliages / Acier inox. réfractaire	Inconel Nimonic Hastelloy	20 30	25 45		<0.2 x ØD ₁	<1 x ØD ₁	0.0003 - 0.0015	0.0010 - 0.004	0.002 - 0.006	0.003 - 0.011	0.005 - 0.021	0.005 - 0.035
S	Titane, alliage de titane		35 60	35 60		<1 x ØD ₁	<1 x ØD ₁	0.0006 - 0.0038	0.0025 - 0.009	0.005 - 0.014	0.007 - 0.026	0.013 - 0.053	0.013 - 0.088
N	Alliage de cuivre / bonne usinabilité (laiton - bronze)		75 150	100 170		<1.5 x ØD ₁	<1 x ØD ₁	0.0010 - 0.0060	0.004 - 0.015	0.008 - 0.023	0.011 - 0.042	0.021 - 0.084	0.020 - 0.140
N	Alliage de cuivre / usinabilité difficile / Bronze à l'aluminium (Ampco)	(CuAlFe)	50 100	60 110		<1 x ØD ₁	<1 x ØD ₁	0.0006 - 0.0038	0.0025 - 0.009	0.005 - 0.014	0.007 - 0.026	0.013 - 0.053	0.013 - 0.088
N	Or, argent		100 150	110 150		<1 x ØD ₁	<1 x ØD ₁	0.0006 - 0.0038	0.0025 - 0.009	0.005 - 0.014	0.007 - 0.026	0.013 - 0.053	0.013 - 0.088

 $D_1 \leq 0.1 \text{ mm} \Rightarrow (ap \& ae) -95 \%$ $D_1 \leq 0.2 \text{ mm} \Rightarrow (ap \& ae) -85 \%$ $D_1 \leq 0.3 \text{ mm} \Rightarrow (ap \& ae) -70 \%$ $D_1 \leq 0.4 \text{ mm} \Rightarrow (ap \& ae) -50 \%$ $D_1 \leq 0.5 \text{ mm} \Rightarrow (ap \& ae) -25 \%$

CONDITIONS DE COUPE - CONTOURNAGE



$$n [\text{tr/min}] = \frac{V_c [\text{m/min}] \times 1000}{\pi \times D_1 [\text{mm}]}$$


$$V_f [\text{mm/min}] = n [\text{tr/min}] \times f_z [\text{mm}] \times Z$$

Avance par dent $f_z [\text{mm}]$

Matières à usiner		CARBURE	C-TOP		ap [mm]	ae [mm]	Avance par dent $f_z [\text{mm}]$						
			Vc [m/min]	Vc [m/min]			$\emptyset D_1$ 0.30 - 1.00	$\emptyset D_1$ 1.00 - 1.50	$\emptyset D_1$ 1.50 - 3.00	$\emptyset D_1$ 3.00 - 6.00	$\emptyset D_1$ 6.00 - 12.00	$\emptyset D_1$ 12.00 - 16.00	
P	Acier non allié / faiblement allié	< 600 N/mm ²		100 200		<2 x $\emptyset D_1$	<0.40 x $\emptyset D_1$	0.0030 - 0.019	0.010 - 0.028	0.014 - 0.053	0.026 - 0.105	0.049 - 0.195	0.090 - 0.260
P	Acier non allié / faiblement allié	600 – 1500 N/mm ²		80 170		<2 x $\emptyset D_1$	<0.30 x $\emptyset D_1$	0.0033 - 0.017	0.009 - 0.025	0.012 - 0.046	0.023 - 0.092	0.043 - 0.172	0.079 - 0.229
P	Acier de décolletage au plomb			120 200		<2 x $\emptyset D_1$	<0.40 x $\emptyset D_1$	0.0045 - 0.023	0.012 - 0.034	0.017 - 0.063	0.032 - 0.126	0.059 - 0.234	0.108 - 0.312
P	Acier fortement allié	700 – 1500 N/mm ²		70 100		<2 x $\emptyset D_1$	<0.30 x $\emptyset D_1$	0.0030 - 0.015	0.008 - 0.023	0.011 - 0.042	0.021 - 0.084	0.039 - 0.156	0.072 - 0.208
M	Acier inoxydable	400 – 700 N/mm ²		80 110		<2 x $\emptyset D_1$	<0.30 x $\emptyset D_1$	0.0030 - 0.015	0.008 - 0.023	0.011 - 0.042	0.021 - 0.084	0.039 - 0.156	0.072 - 0.208
M	Acier inox. DUPLEX, acier austénitique inox. sans nickel > 800 N/mm ²			50 80		<2 x $\emptyset D_1$	<0.30 x $\emptyset D_1$	0.0023 - 0.011	0.006 - 0.017	0.008 - 0.032	0.016 - 0.063	0.030 - 0.117	0.048 - 0.156
K	Fonte grise / Fonte à graphite sphéroïdal perlite	< 250 HB	120 150	160 200		<2 x $\emptyset D_1$	<0.40 x $\emptyset D_1$	0.0045 - 0.023	0.012 - 0.034	0.017 - 0.063	0.032 - 0.126	0.059 - 0.234	0.108 - 0.312
K	Fonte alliée / Fonte à graphite sphéroïdal perlite	> 250 HB	100 130	130 170		<2 x $\emptyset D_1$	<0.30 x $\emptyset D_1$	0.0033 - 0.017	0.009 - 0.025	0.012 - 0.046	0.023 - 0.092	0.043 - 0.172	0.079 - 0.229
K	Fonte à graphite sphéroïdal ferritique / Fonte malléable		80 110	110 150		<2 x $\emptyset D_1$	<0.30 x $\emptyset D_1$	0.0033 - 0.017	0.009 - 0.025	0.012 - 0.046	0.023 - 0.092	0.043 - 0.172	0.079 - 0.229
S	Super alliages / Acier inox. réfractaire	Inconel Nimonic Hastelloy	20 45	30 60		<2 x $\emptyset D_1$	<0.15 x $\emptyset D_1$	0.0015 - 0.008	0.004 - 0.011	0.006 - 0.021	0.011 - 0.042	0.020 - 0.078	0.036 - 0.104
S	Titane, alliage de titane		45 75	50 80		<2 x $\emptyset D_1$	<0.30 x $\emptyset D_1$	0.0038 - 0.019	0.010 - 0.028	0.014 - 0.053	0.026 - 0.105	0.049 - 0.195	0.090 - 0.260
N	Alliage de cuivre / bonne usinabilité (laiton – bronze)		90 130	120 200		<2 x $\emptyset D_1$	<0.40 x $\emptyset D_1$	0.0060 - 0.030	0.016 - 0.045	0.023 - 0.084	0.042 - 0.168	0.078 - 0.312	0.144 - 0.416
N	Alliage de cuivre / usinabilité difficile / Bronze à l'aluminium (Ampco)	(CuAlFe)	70 120	80 140		<2 x $\emptyset D_1$	<0.40 x $\emptyset D_1$	0.0038 - 0.019	0.010 - 0.028	0.014 - 0.053	0.026 - 0.105	0.049 - 0.195	0.090 - 0.260
N	Or, argent		140 190	150 200		<2 x $\emptyset D_1$	<0.40 x $\emptyset D_1$	0.0038 - 0.019	0.010 - 0.028	0.014 - 0.053	0.026 - 0.105	0.049 - 0.195	0.090 - 0.260

 $D_1 \leq 0.1 \text{ mm} \Rightarrow (ap \& ae) -95 \%$ $D_1 \leq 0.2 \text{ mm} \Rightarrow (ap \& ae) -85 \%$ $D_1 \leq 0.3 \text{ mm} \Rightarrow (ap \& ae) -70 \%$ $D_1 \leq 0.4 \text{ mm} \Rightarrow (ap \& ae) -50 \%$ $D_1 \leq 0.5 \text{ mm} \Rightarrow (ap \& ae) -25 \%$

CONDITIONS DE COUPE - RAINURAGE



$$n [\text{tr/min}] = \frac{V_c [\text{m/min}] \times 1000}{\pi \times D_1 [\text{mm}]}$$

$$V_f [\text{mm/min}] = n [\text{tr/min}] \times f_z [\text{mm}] \times Z$$

Avance par dent $f_z [\text{mm}]$

Matières à usiner		CARBURE		C-TOP		ap [mm]	ae [mm]	Avance par dent $f_z [\text{mm}]$					
		Vc [m/min]	Vc [m/min]	Vc [m/min]	Vc [m/min]			Ø D ₁ 0.30 - 1.00	Ø D ₁ 1.00 - 1.50	Ø D ₁ 1.50 - 3.00	Ø D ₁ 3.00 - 6.00	Ø D ₁ 6.00 - 12.00	Ø D ₁ 12.00 - 16.00
P	Acier non allié / faiblement allié	< 600 N/mm ²		75 150		<2 x ØD ₁	<1 x ØD ₁	0.0012 - 0.008	0.004 - 0.011	0.006 - 0.021	0.011 - 0.0426	0.020 - 0.078	0.036 - 0.104
P	Acier non allié / faiblement allié	600 - 1500 N/mm ²		60 130		<1.5 x ØD ₁	<1 x ØD ₁	0.0013 - 0.007	0.004 - 0.010	0.005 - 0.018	0.009 - 0.037	0.017 - 0.069	0.032 - 0.092
P	Acier de décolletage au plomb			90 150		<2 x ØD ₁	<1 x ØD ₁	0.0018 - 0.009	0.005 - 0.014	0.007 - 0.025	0.013 - 0.050	0.023 - 0.094	0.043 - 0.125
P	Acier fortement allié	700 - 1500 N/mm ²		50 75		<1 x ØD ₁	<1 x ØD ₁	0.0012 - 0.006	0.003 - 0.009	0.005 - 0.017	0.008 - 0.034	0.016 - 0.062	0.029 - 0.083
M	Acier inoxydable	400 - 700 N/mm ²		60 80		<1 x ØD ₁	<1 x ØD ₁	0.0012 - 0.006	0.003 - 0.009	0.005 - 0.017	0.008 - 0.034	0.016 - 0.062	0.029 - 0.083
M	Acier inox. DUPLEX, acier austénitique inox. sans nickel > 800 N/mm ²			40 60		<0.8 x ØD ₁	<1 x ØD ₁	0.0009 - 0.005	0.002 - 0.007	0.003 - 0.013	0.006 - 0.025	0.012 - 0.47	0.019 - 0.062
K	Fonte grise / Fonte à graphite sphéroïdal perlite	< 250 HB	90 160	120 200		<2 x ØD ₁	<1 x ØD ₁	0.0018 - 0.009	0.005 - 0.014	0.007 - 0.025	0.013 - 0.050	0.023 - 0.094	0.043 - 0.125
K	Fonte alliée / Fonte à graphite sphéroïdal perlite	> 250 HB	75 100	90 130		<1 x ØD ₁	<1 x ØD ₁	0.0013 - 0.007	0.004 - 0.010	0.005 - 0.018	0.009 - 0.037	0.017 - 0.69	0.032 - 0.092
K	Fonte à graphite sphéroïdal ferritique / Fonte malléable		60 80	80 110		<1 x ØD ₁	<1 x ØD ₁	0.0013 - 0.007	0.004 - 0.010	0.005 - 0.018	0.009 - 0.037	0.017 - 0.69	0.032 - 0.092
S	Super alliages / Acier inox. réfractaire	Inconel Nimonic Hastelloy	20 30	25 45		<0.2 x ØD ₁	<1 x ØD ₁	0.0006 - 0.003	0.002 - 0.005	0.002 - 0.008	0.004 - 0.017	0.008 - 0.031	0.014 - 0.042
S	Titane, alliage de titane		35 60	35 60		<1 x ØD ₁	<1 x ØD ₁	0.0015 - 0.008	0.004 - 0.011	0.006 - 0.021	0.011 - 0.042	0.020 - 0.078	0.036 - 0.104
N	Alliage de cuivre / bonne usinabilité (laiton - bronze)		75 150	100 170		<2 x ØD ₁	<1 x ØD ₁	0.0024 - 0.012	0.006 - 0.018	0.009 - 0.034	0.017 - 0.067	0.031 - 0.125	0.058 - 0.166
N	Alliage de cuivre / usinabilité difficile / Bronze à l'aluminium (Ampco)	(CuAlFe)	50 100	60 110		<1.5 x ØD ₁	<1 x ØD ₁	0.0015 - 0.008	0.004 - 0.011	0.006 - 0.021	0.011 - 0.042	0.020 - 0.078	0.036 - 0.104
N	Or, argent		100 150	110 150		<1 x ØD ₁	<1 x ØD ₁	0.0015 - 0.008	0.004 - 0.011	0.006 - 0.021	0.011 - 0.042	0.020 - 0.078	0.036 - 0.104

 $D_1 \leq 0.1 \text{ mm} \Rightarrow (ap \& ae) -95 \%$ $D_1 \leq 0.2 \text{ mm} \Rightarrow (ap \& ae) -85 \%$ $D_1 \leq 0.3 \text{ mm} \Rightarrow (ap \& ae) -70 \%$ $D_1 \leq 0.4 \text{ mm} \Rightarrow (ap \& ae) -50 \%$ $D_1 \leq 0.5 \text{ mm} \Rightarrow (ap \& ae) -25 \%$